

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Inspection Report Minerals Regulatory Program May 30, 2013

Reviewed:

Mine Name: D-TractPermit Number: S/047/0068Operator Name: Uintah Basin ResourcesInspection Date: May 30, 2013Inspector(s): April Abate & Paul BakerTime: 2:00 PMOther Participants: NoneMine Status: Active

	Elements of Inspection	Evaluated	Comment	Enforcemen
1.	Permits, Revisions, Transfer, Bonds			
2.	Public Safety (shafts, adits, trash, signs, highwalls)			
3.	Protection of Drainages / Erosion Control			
4.	Deleterious Material			
5.	Roads (maintenance, surfacing, dust control, safety)			
6.	Reclamation			
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	\square		
8.	Soils	$\overline{\boxtimes}$	$\overline{\boxtimes}$	
9.	Revegetation	$\overline{\boxtimes}$	$\overline{\boxtimes}$	

Permit Fees: not due site is in reclamation Bond Amount: Surety 14,500

Purpose of Inspection:

The purpose of the inspection is to introduce new lead, April Abate to the site.

Inspection Summary:

Photos were taken to document site conditions.

No mining activity was observed during the time of inspection at the site. According to Paul, the operator has begun reclamation by backfilling the pit area. The operator reportedly seeded the area in the spring of 2011; however the seeding did not appear to take very successfully.

Conclusions and Recommendations:

The operator should attempt to seed the area in accordance with the reclamation guidelines outlined by the Division and posted on the Division's website. Until the operator can demonstrate three successful growing seasons, a full bond release cannot be granted. See manual on the Practical Guide to Reclamation in Utah:

https://fs.ogm.utah.gov/pub/mines/coal_related/RecMan/Reclamation_Manual.pdf

Inspector's Signature

cc: Tar Sands Holdings, LLC


O:\M047-Uintah\S0470068-Wembco\inspections\Insp_053013.doc






05/30/2013

View of backfill reclamation of the pit area. Vegetation growth is spotty.





Current activity at the site.




Figure 1. Aerial circa 2010